Name(s) of Risk Team Members: A. Piper			Point Value → Parameter ↓		1			2	3	4			5			
Area/Facility Description Title: Collider-Accelerator Siemens and Westinghouse M.G. Sets (buildings 911, 928)			Occupancy or Use		≤once/year				≤once/month	≤once/week ≤once/shift		>once/shift				
Area/Facility # (if applicable): Area-Wide FRA 8 Area/Facility Description: Area-Wide for Siemens and Westinghouse M.G. Sets (buildings 911, 928)		Severity	F	First Aid Only			N	Medical Treatment	Lost Time	Partial Disability			I	Death or Permanent Disability		
Approved by: E. Lessard Date: 6/3/04 Rev.#: 0			Likelihood	Impossible			le		Unlikely	Possible Probable				Multiple		
Reason for Revision (in	f applicable):									Comments:						
					Ве		Additi			After Add Contr			Additiontrols	trols		
Physical Item or Activity	Hazard(s)	Control(s)			Occupancy A	Severity B	Likelihood C	Risk* AxBxC	Contro	ol(s) Added to Reduce Risk		Occupancy A	Severity B	Likelihood C	Risk* AxBxC	% Risk Reduction
Electrical Equipment & Power Supplies BNL Class A & B <250 VAC; <1000Vdc	Shock or electrocution	All equipment is listed or reviewed by CEE; Tier 1 inspections; disconnected cable policy; installations comply with applicable codes; procedures; training; distribution drawings; LOTO; Kirk keys; working hot permits; qualified electricians and technicians; cabinet interlocks; postings; locked areas; guarding; work planning; GFCI; grounding standards; emergency procedures			5	4	2	40								
Electrical Equipment & Power Supplies BNL Class C <600 VAC; <6000 VDC	Arc blast; burn	Procedures, training, PPE	and processing		3	5	2	30								
Electrical Disconnects And Switches	Arc blast; burn	Procedures, training, PPE			2	4	3	24								
Electrical Disconnects And Switches	Shock or electrocution	All equipment is listed or reviewed inspections; disconnected cable pol with applicable codes; procedures; drawings; LOTO; Kirk keys; worki electricians and technicians; cabine locked areas; guarding; work plann standards; emergency procedures; t work	icy; installations completed in the complete in the complete in the complete interlocks; postings; ing; GFCI; grounding	ed	2	5	2	20								
Motor Control Centers; Panels And Wall Sockets	Shock or electrocution	All equipment is listed or reviewed inspections; disconnected cable pol with applicable codes; procedures; drawings; LOTO; Kirk keys; worki ASSRC/ESRC reviews; qualified e technicians; cabinet interlocks; post guarding; work planning; grounding	icy; installations complete icy; installations complete icy; distribution ng hot permits; lectricians and ings; locked areas;	ly	4	5	2	40								
Motor Control Centers; Panels And Wall Sockets	Arc blast; burn	PPE; training; procedures			4	4	2	32								

T1 + 1 1 7 1		Tage	Ι.		Τ -	0.5	
Electrical Powered Hand Tools	Shock or electrocution	All equipment is listed or reviewed by CEE; Tier 1 inspections; procedures; training; labeling; work planning; GFCI; grounding standards; double insulation	4	3	3	36	
Extension Chords; Temporary Wiring And Power Strips	Shock or electrocution	All equipment is listed or reviewed by CEE; Tier 1 inspections; disconnected cable policy; installations comply with applicable codes; procedures; training; distribution drawings; qualified electricians and technicians; GFCI; grounding standards	4	3	3	36	
Lighting	Poor visibility	Tier 1 inspections; maintenance; emergency lighting; temporary lighting	3	2	3	18	
Lighting	Falls on same level	Tier 1 inspections; maintenance; emergency lighting; temporary lighting	3	3	3	27	
Lighting	Being struck against an object, such as a carpenter walking into a door frame, or cuts and bruises from working in tight spaces	Tier 1 inspections; maintenance; emergency lighting; temporary lighting	2	3	3	18	
Material Handling	Bodily reaction – injuries resulting from bending, climbing, loss of balance and slipping without falling	Use of dollies to eliminate manual material handling tasks, ergonomic reviews of work, effective supervision at the job site, training	3	3	3	27	
Chemical Handling	Eye exposure	Procedures; compliance with regulations; training; CMS inventory; MSDS; volume controls; PPE as required; locked or controlled areas; postings; labeling; proper containers; segregation; proper spill cleanup equipment available; Tier 1 inspections	3	4	2	24	
Chemical Handling	Inhalation exposure	Procedures; compliance with regulations; training; CMS inventory; MSDS; volume controls; PPE as required; locked or controlled areas; postings; labeling; proper containers; segregation; proper spill cleanup equipment available; Tier 1 inspections	3	3	2	18	
Chemicals	Fire; explosions	Procedures; compliance with regulations; training; CMS inventory; MSDS; volume controls; PPE as required; locked or controlled areas; postings; labeling; proper containers; segregation; proper spill cleanup equipment available; Tier 1 inspections	3	2	2	12	
Chemical Handling	Burns	Procedures, compliance with regulations, training, CMS inventory, MSDS, volume controls, Fire/Rescue group response, PPE as required, locked or controlled areas, postings, labeling, proper containers, segregation, spill cleanup equipment available, Tier 1 inspections	3	3	2	18	
Remotely Operated Equipment	Becoming caught in or compressed by equipment	Postings; barriers; guards; maintenance; training; work planning; procedures; Tier 1 inspections	2	4	3	24	
Use Of Hand Tools	Being struck by an object, such as flying chips, rotating parts	PPE; training; maintenance; Tier 1 inspections; UL listed equipment; pre-inspections; equipment specific training; guarding; PPE; postings	4	2	3	24	
Use Of Hand Tools	Being struck against an object or cuts and bruises from working in tight spaces or near sharp surfaces	PPE; training; guarding	4	2	3	24	
Use of hand tools	Electrical shock	GFCI, grounding cases or insulated cases	4	3	2	24	

Use of hand tools	Overexertion – injuries caused by excessive lifting, pushing,	PPE, Training, work planning, procedures, proper equipment	4	3	3	36						
	pulling, holding, carrying or throwing of an object											
Noise	Hearing loss	Training; hearing protection; noise surveys; procedures; postings; medicals; engineered noise reduction; work planning; locked areas with limited access to authorized personnel only	4	3	4	48						
Manual Material Handling	Overexertion – injuries caused by excessive lifting, pushing, pulling, holding, carrying or throwing of an object	Gloves; hardhat; handcarts; dollies; training; safety shoes	4	3	3	36						
Confined Spaces	Entrapment, engulfment, exposure to dangerous atmospheres.	Barriers, postings, training, Confined Spaces Permits, work planning, procedures, Tier 1 inspections	2	5	2	20						
Walking – Working Surfaces	Falls on same level	PPE; Tier 1 inspections; work planning; P.E. scheduled maintenance; internal and external audits; posting; labeling; training; barriers; communication; lessons learned	5	4	3	60	C-A staff was asked to identify outside walking/working surfaces that are in need of repair. PE instituted a program to correct deficiencies. Snow shovels and salt were distributed to staff and users for emergency use on walkways in winter storms. A safety checklist: Walking and Working Surfaces was distributed to staff. C-A O.P.M. 2.28.d was updated to indicate that work performed with risk factors of slipping and falling shall be classified at a minimum as a moderate hazard job and will require additional review and an Enhanced Work Permit.	5	4	2	40	50%
Pressurized Systems	Being struck by an object, such as flying debris due to pressure release	Postings, PPE, maintenance, training, work planning, Cryogenic Safety Committee /ASSRC reviews, procedures, interlock systems, Certification/testing of pressure related equipment, Tier 1 inspections, LOTO, C-AD Chief ME reviews, codes and standards usage	4	3	3	36						
Hydraulics	Being struck by an object, such as flying debris due to pressure release	Design reviews, ESRC/ASSRC reviews, pressure testing, LOTO, work planning, PPE, training, procedures, posting labeling	3	4	3	36						
Hydraulics	Falls on same level	Design reviews, ESRC/ASSRC reviews, pressure testing, LOTO, work planning, Tier 1 inspections	3	4	3	36						
Hydraulics	Fire	Design reviews, ESRC/ASSRC reviews, proof testing, LOTO, work planning, PPE, training, Fire/Rescue Group response	3	4	2	24						
Moving Items with Cranes	Being struck by an object, such as a tool falling on a worker from above	Training, daily crane inspections prior to use, PE crane maintenance, PPE, certified rigging equipment, Tier 1 inspections, yearly rigging inspections, load weights and center of gravity known prior to lift, procedures, qualified riggers if required, critical lift and engineered lift requirements and reviews, warning alarms, postings, work planning, load testing, barriers	3	5	2	30						
Electrical Caged Area/ Rooms	Electrical shock	Locked areas, procedures, electrical safety training, control zones (e.g. signs and barriers), work permits, job safety analysis, LOTO, safety watch, working hot permits, equipment design review, scheduled maintenance of equipment, fire rescue response, EMTs, work planning, PPE	2	5	2	20						
Batteries/UPS	Electrical shock, molten spray	PPE; procedures; training	4	2	2	16						

Batteries/UPS	Electrical shock, hydrogen gas explosion	PPE; procedures; training, ventilation	4	3	2	24						
Motor Generators, Liquid rheostat chain drive	Becoming caught in or compressed by equipment	Equipment specific training, machine guards, PPE, postings, maintenance, Tier 1 inspections, barriers, procedures, checklists	4	4	3	48						
Working with compressed air	Being struck by an object, such as flying debris due to pressure release	PPE, pressure reducing nozzles	3	3	2	18						
Work At Heights	Falls to lower level, such as falling from a ladder or over a railing	Postings; barriers; fall protection; maintenance; training; work planning; procedures; Tier 1 inspections; PPE; approved scaffolding and platforms; approved ladders; antislip surfaces	2	5	2	20						
Further Description of	Further Description of Controls Added to Reduce Risk:											
*Risk:	0 to 20	21 to 40	41-60		1-60		61 to 80		81 or gre	ater		
	Negligible	Acceptable	Mode	Moderate			Substantial		Intolerable			